

1000 Eagle Gate Tower, 60 East South Temple | Salt Lake City, Utah 84111

Tel: (801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com

AUG 1 4 2008

PATENT Docket No. 15436.247.35.1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of

Certificate

DiJaili et al.

AUG 1 8 2008

Serial No.:

10/020,527

of Correction

Filed:

Dec. 14, 2001

Art Unit 3663

For:

OPTICAL CROSSBAR USING LASING

SEMICONDUCTOR OPTICAL AMPLIFIERS

Examiner:

Mark Hellner

Patent No.:

7,046,434 B1

Issue Date:

May 16, 2006

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323

Attn: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313–1450

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

08/14/2008 HALI33 01 FC:1811 RECEIVED-USPTO 00000014.27464324icstion 100.00 0P AUG 1 8 2008

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23–3178. Duplicate copies of this letter are enclosed.

Dated this b day of August, 2008.

Respectfully submitted,

R. Burns Israelsen Attorney for Patentee Registration No. 42,685 Customer No. 022913

RBI:jsb Docket No. 15436.247.35.1 Certificate of Correction Documents (with check)

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313–1450, on this 12 day of 4008.

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323,

PTO Form 1050 and Check No. for \$100.00

159325



1000 Eagle Gate Tower, 60 East South Temple | Salt Lake City, Utah 84111

Tel: (801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com

PATENT Docket No. 15436.247.35.1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of

DiJaili et al.

Serial No.:

10/020,527

Filed:

Dec. 14, 2001

Art Unit 3663

For:

OPTICAL CROSSBAR USING LASING

SEMICONDUCTOR OPTICAL AMPLIFIERS

Examiner:

Mark Hellner

Patent No.:

7,046,434 B1

Issue Date:

May 16, 2006

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323

Attn: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

RECEIVED-USPTO
Patent Publication

AUG 1 8 2008

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23-3178. Duplicate copies of this letter are enclosed.

Dated this barren day of August, 2008.

Respectfully submitted,

2. Burstul

R. Burns Israelsen Attorney for Patentee Registration No. 42,685 Customer No. 022913

RBI:isb Docket No. 15436.247.35.1 Certificate of Correction Documents (with check)

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on this 12 day of August 2008.

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323, PTO Form 1050 and Check No. ________ for \$100.00

159325

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 1 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006

INVENTOR(S)


: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title Page

Item 56, Page 2, Other Publications, Column 1, Line 42, change "Jong" to --Jeong--

Sheet 2, change "Figure 2" to the figure depicted herein below, wherein the reference "201" has been removed.



Feature 2

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2008

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 2 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006

INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 6, change "Figure 4C" to the figure depicted herein below, wherein the Top Cladding Layer has been labeled --407--




Figure 4C

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

Pakera Publication AUG 1 8 2008

RECLIV ..

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)


: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 11, change "Figure 7A" to the figure depicted herein below, wherein the NAND gate has been labeled -- 700--





Optical NAND Gate 700

Figure 7A

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 12, change "Figure 7B" to the figure depicted herein below, wherein the 2nd and 3rd row of the outputs have been change to -1-- and --0--, and --0-- and --1--, respectively.



8	R	Q	ā	
Ď	٥	4	1	Not Used
0	1	1	0	
*	0	0	1	 -
1	1	0 1	1 0	Memory State

Optical File-Flop

Figure 78

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

ECLIVE LANGE

AUG 1 8 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 5 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 13, change "Figure 7C" to the figure depicted herein below, wherein the 3rd and 4th row of the outputs have been change to --1-- and --0--, and --0-- and --1--, respectively.



D	Enskila		a a	
0	Ģ		Memory State	-
Ŷ	0		Mornory State	***
0	i		1 0	_
1		П	n 1	_

Optical Buffer Element Figure 7C

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2008

Laurence and mark a real

Mill Section

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 6 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006

INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 53, change "115" to --110--

Column 11

Line 5, change "421" to --412--

Line 24, change "410" to --310--

Line 25, change "220" to --320--

Line 40-41, change "10 dB" to --20 dB--

Line 43, change "30 dB" to -60 dB-

Column 12

Line 17, change "510" to --110--

Column 15

Line 18, change "FIG. 17B" to --FIG. 7B--

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2008

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DOC Code: COCIN

: 7,046,434 B1

Page 1 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006

INVENTOR(S)


: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title Page

Item 56, Page 2, Other Publications, Column 1, Line 42, change "Jong" to --Jeong--

Sheet 2, change "Figure 2" to the figure depicted herein below, wherein the reference "201" has been removed.



Floure 2

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 8 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 2

of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 6, change "Figure 4C" to the figure depicted herein below, wherein the Top Cladding Layer has been labeled --407--



Verical Lasing Semiconductor Optical Amplifier 400

Figure 4C

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111 RECEIVE AND STAN

AUG 1 8 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

Page 3 of 6

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)


: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 11, change "Figure 7A" to the figure depicted herein below, wherein the NAND gate has been labeled -- 700--





Optical NAND Gate 700

Figure 7A

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

الكشف السياء والمستدين

AUG 1 8 2003

Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DOC Code: COCIN

: 7,046,434 B1

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 12, change "Figure 7B" to the figure depicted herein below, wherein the 2nd and 3rd row of the outputs have been change to --1-- and --0--, and --0-- and --1--, respectively.



	. R	. 24	Q	ā	
Ć	Ò		1	1	Not Used
-0) 1		1	0	
	0	- 18	0	1	
1	1		0 1	*	Memory State

Optical File-Flop

Figure 78

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2003

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006


INVENTOR(S)

: DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 13, change "Figure 7C" to the figure depicted herein below, wherein the 3rd and 4th row of the outputs have been change to --1-- and --0--, and --0-- and --1--, respectively.



Ð	Enatora	c o
0	Q.	Memory State
Ü	Ö	Momory State
ø	•	1 0
4		n 1

Optical Buffer Element Figure 7C

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

AUG 1 8 2008

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,046,434 B1

APPLICATION NO. : 10/020,527

ISSUE DATE

: May 16, 2006

INVENTOR(S)

; DiJaili et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 53, change "115" to --110--

Column 11

Line 5, change "421" to --412--

Line 24, change "410" to --310--

Line 25, change "220" to --320--

Line 40-41, change "10 dB" to --20 dB--

Line 43, change "30 dB" to --60 dB--

Column 12

Line 17, change "510" to --110--

Column 15

Line 18, change "FIG. 17B" to --FIG. 7B--

MAILING ADDRESS OF SENDER (Please do not use customer number

R. Burns Israelsen, Esq., WORKMAN NYDEGGER 1000 Eagle Gate Tower **60 East South Temple** Salt Lake City, Utah 84111

AUG 1 8 2008